



[illegible]

A diagram of a three-phase motor. It shows a cylindrical motor body with a flange on the right. A label 'N' is at the top left, pointing to a terminal. A label 'C' is on the right, pointing to the flange. Three labels '1', '2', and '3' are at the bottom left, pointing to three separate terminals.

ITEM	UNID.	DESCRIÇÃO
1	CA	RELE PROTETOR
2	CA	BASE FERRUGEM COM 1 RELE
3	CA	BOBINA DE INTERRUPTOR COM 1 RELE
4	PC	BOBINA DE INTERRUPTOR 3/4" x 1/2"
5	PC	FERRAGEM-CABO 3/4" x 1/2"
6	PC	CONDUITE TIPO 1/2" OU 3/4"
7	PC	POINTE DE PASSAGEM TIPO "SMALL"
8	PC	SUPOORTE EM PLAST. 1/2"
9	PC	PARAFUSO CHAVECA SEMIFURADO 1/4" x 1"

DETALHE
S/BOBINA

[illegible][illegible]